

RoSPA Safety Inspection Report –

Comments/observations regarding the tasks highlighted within the report (please refer to report attached)

Agility Trail (pg. 7)

Decay to timber components – replace decayed components where possible

Contractor or OCC – **Contractor (Eastwick)**

Basketball Post (pg.9 and 10)

Hoop bent – noted and straightened.

Weeds – to be removed – noted, will pull these up.

Multiplay (pg.13 and 14)

Cap missing – **Tony has some caps, will replace missing one/s**

Holes in step backing material

Contractor or OCC - **Tony and Peter to repair backing material**

Protective surface under all bars and rings must be kept in good condition – **Tony and I didn't understand this task i.e. where it referred to Any ideas?**

Multiplay cont'd (pg. 15)

Timber decayed – ramp post

Replace affected parts

Contractor or OCC - **Contractor**

Plywood at the top of the slide is not in a good condition.

Replace plywood

Contractor or OCC – **Contractor**

Daisy Rocker/Motorcycle Rocker (pg. 18 and 19)

Rub down and treat damaged edges/spring and mounting plate

These items would benefit from rubbing down and painting

Contractor or OCC – **OCC springtime**

Swing nest (pg. 24)

Excessive wear on shackles, bushes and associated connections

Replace

Contractor or OCC – replaced by Tony and Peter

Toddler swing (pg.25)

Wear in bushes

Remove shackle bolt and back bush and shackle pin wear

Contractor or OCC – **Tony has checked bush and shackle – no replacements required.**

Toddler swing cont'd (pg. 26)

Replace decayed timber (edging)

Contractor or OCC – **Contractor**

Goal Post (pg.27)

Replace decayed timber

Contractor or OCC – **Contractor**

Grassed area below goal post (pg. 28)

Make good grassed area?? Should this be filled and seeded?