Maintenance check of automated external defibrillator located on the wall of the Football Pavilion – 21st September 2020 – Clerk and Cllr Lynch

The following tests were carried out:

- Rescue Ready Indicator Green, not action needed. The AED is ready to use (if the indicator, which can be viewed through the viewing window of the outer box, was red, refer to user guide).
- \checkmark Check the voice prompts work and the display is readable
- \checkmark Check that the defibrillation pads are ready for use and the service beep sounds
- ✓ Check that the LEDs work
- ✓ Check that the buttons work
- ✓ Check the AED case for signs of stress

A replacement battery was fitted to the alarm inside the external box and tested.

A new battery will need to be purchased by April next year for the AED. The cost of this would be approximately £300 (currently) inclusive of vat.

A monthly visual check could be carried out and recorded whilst the Play equipment inspection is carried out (to check the Rescue Ready Indicator is green <u>not</u> red. A six monthly check will be carried out by the Clerk and Cllr Lynch.