

Area 1 – Wrexham road near Overton village sign

Large collections of leaves and soil/debris obstructing the footpath from the entrance to the Playingfields to Argoed lane junction (up to 50% of the footpath, 100 metres long in the worse area, as shown, near the village sign)



Area 2 – Wrexham road, on the top end of the hill

Total obstruction of the footpath in places by well-established weeds, grass and turf extending several metres



Area 3 – Brow of Overton Hill at junction with Argoed Lane

Suspected HGV damage to pathway



Area 4 – Wrexham road at the entrance to the Catholic Church

Pavement and pathway is badly cracked and broken up

